



Date: Mar-2017

# **Service Bulletin**

## **TECHNICAL**

Subject: (HYBRID) No Start, EV, BAS3 eAssist Red Battery Light/Charging System Light On, Malfunction Indicator Lamp (MIL) Illuminated - DTC P1F17 Set

| Brand:    | Model:         | Model Year: |      | VIN: |    | Engine: | Transmission: |
|-----------|----------------|-------------|------|------|----|---------|---------------|
|           |                | from        | to   | from | to |         |               |
| Cadillac  | СТ6            | 2016        | 2017 |      |    | LTG     | MRD           |
| Chevrolet | Bolt EV        | 2017        | 2017 |      |    | MMF     | MMF           |
|           | Malibu (VIN Z) | 2016        | 2016 |      |    | LKN     | MKE           |
|           | Malibu         | 2017        | 2017 |      |    | LKN     | MKE           |
|           | Silverado      | 2016        | 2017 |      |    | L8B     | M5X           |
| GMC       | Sierra         | 2016        | 2017 |      |    | L8B     | M5X           |

| Involved Region or Country | North America, Korea, Europe   |  |  |
|----------------------------|--|--|--|
| Additional Options (RPOs)  | HP4, HP5, HP9, K23   |  |  |
| Condition                  | Some customers may comment on one or more of the following conditions:  No start  Battery light on/Charging System Light  Tow vehicle in  MIL illuminated  The technician may find DTC P1F17 set.                                  |  |  |
| Cause                      | This condition may be caused by a timing issue between the BCM, SDM and HPCM2.   |  |  |
| Correction                 | An updated software calibration has been released to address these concerns. Reprogram the Hybrid Powertrain Control Module 2 (HPCM) using the Service Programming System (SPS) with the latest calibrations available on TIS2WEB. |  |  |

### **Parts Information**

No parts are required for this repair.

### **Warranty Information**

| Labor Operation | Description   | Labor Time                            |
|-----------------|---|---------------------------------------|
| 2810265         | Hybrid Powertrain Control Module 2 Reprogramming with SPS | Use Published Labor Operation<br>Time |

#### **Service Procedure**

**Important:** Stable battery voltage is critical during programming. Any fluctuation, spiking, over voltage or loss of voltage will interrupt programming. Install the *EL-49642* SPS Programming Support Tool to maintain system voltage. If not available, connect a fully charged 12 V jumper or booster pack disconnected from the AC voltage supply. **DO NOT** connect a battery charger.

Perform HPCM update. Refer to Hybrid Powertrain Control Module 2 Programming and Setup in SI.

| Version  | 1 |
|----------|---|
| Modified |   |

Additional Keywords:P1F17, BAS3, eAssist, Hybrid, HEV4, PHEV, EV, Bolt EV, Bolt, Plug-in, HPCM2

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.

